



# D&D Facility Characterization Interview Checklist

ID No.: 714A

Date: 10/09/00

Page 1 of 2

## Check List for - Title: D&D Facility Characterization - Interviews

- CRITERIA:**
- Δ *D&D Characterization Protocol*, RFETS MAN-077-DDCP, Rev. 0
  - Δ *Facility Disposition Program Manual*, RFETS MAN-076-FDPM
  - Δ RFETS Radiological Safety Practices, January 12, 1998

**Facility Name & Type (1, 2, or 3)** Buildings 714A, Type 1 Facility, HF Storage Shed

**Personnel Interviewed (Name & Title/Function)** Don L. Cox, Mechanical Engineer V, D&D Closure

-- Y/ N

Does a current WSRIC exist for the facility? ..... N

If so, are there exceptions to the WSRIC as written? ..... No Exceptions

COMMENTS (incl. WSRIC contacts)

WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.

Are rad surveys available that indicate current status of the facility? ..... N

Are historical rad surveys available that indicate historical status, or evolution, of the facility? ..... N\*

COMMENTS N\* According to Sarah J. Roberts, X3008, ARCD, T771Q, any historical data, which is probably at the Federal Center, would not be adequate for unrestricted release (i.e. Pre-Demolition Survey or Property Release Evaluation). New monitor surveys would have to be taken.

Is an HRR available for the facility? ..... Y

Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further

Characterize the facility relative to chemical &/or radiological contamination? ..... N

Are engineering drawings (esp. "as-builts") available? ..... Y

Are any nonconformances or issues with the facility status currently being tracked in PATS? ..... N

If so, what are the issues (note in Comments, below)?

COMMENTS The building does not sit on IHSS/ PAC area land /soil

Have any types of chemical characterization, incl. asbestos, been performed recently? ..... N

If so, what types of characterization were performed (note in Comments, below)?

COMMENTS No asbestos characterization data exists. The building is a metal shed with no equipment in it.

Interviewed by: D. A. Burton / [Signature] / 10/09/00

Print Name

Signature

Interview Date



# D&D Facility Characterization Interview Checklist

ID No.: 714A

Date: 10/09/00

Page 2 of 2

What timeframe did the interviewee work in the facility? N/A. The building is a storage shed.

Has the building configuration changed since you worked in the building? If so, in what way?  
No.

What types of equipment were in the building during the interviewee's time there?  
No equipment. Building only has concrete storage pillars to hold the HF cylinders.

Where was the equipment located? (specific rooms/areas) In the shed.

Were any radioactive materials or metals handled in the building? If so, what types? No

Which equipment handled radioactive material? None

Were any chemicals handled in the building? If so, what types? Yes. Anhydrous HF cylinders were stored here.

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No

Were these spills/releases cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: D. A. Burton / *D. A. Burton* / 10/09/00  
Print Name Signature Interview Date



2/2